

Hynson House
(Kingsway Center Commercial Area)
1314 Aubert
St. Louis
St. Louis County
Missouri

HABS No. MO-60-T

HABS
MO,
96-SALU,
133-T-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA



Historic American Buildings Survey
National Park Service
Rocky Mountain Regional Office
Department of the Interior
P.O. Box 25287
Denver, Colorado 80225

**NATIONAL PARK SERVICE
ROCKY MOUNTAIN REGION**

HABS MO, 96-SALU, 133-T-


ARCHITECTURAL DATA FORM

STATE MISSOURI		COUNTY	TOWN OR VICINITY CITY OF SAINT LOUIS
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Hynson House (Assessor's Records)			HABS NO. MO-60-T
SECONDARY OR COMMON NAMES OF STRUCTURE			
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 1314 Aubert			
DATE OF CONSTRUCTION (INCLUDE SOURCE) 1894 (Assessor's Records)		ARCHITECT(S) (INCLUDE SOURCE) No records found.	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The Kingsway Center Area is locally significant for its architectural significance as an important representative illustration of neighborhood development and urban vernacular building traditions in late 19th-century St. Louis. The Hynson House is one of the buildings in the area that contributes to a potential historic district. Original Use: single-family residence			
STYLE (IF APPROPRIATE) Queen Anne			
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Stone foundation. Full basement w/concrete floor. Brick walls. Masonry bldg. frame. Galvanized gutters & downspouts. Hip roof, asphalt shingle. Hardwood floors. Plaster & dry wall walls & ceilings. Cast iron & galvanized plumbing. Gas forced warm air heating. Incandescent lighting. fuse box.			
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Floor plan attached.			
EXTERIOR FEATURES OF NOTE Building has hipped dormer with carved wood brackets. Contains square windows with diamond-point rustication surround. 1st floor window has rusticated segmental arch and rusticated course at impost. Door with glass-bricked sidelight. Windows have wood frames. Side windows have segmental arches and round window in foundation.			
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Floor plan attached			
MAJOR ALTERATIONS AND ADDITIONS WITH DATES No records found			
PRESENT CONDITION AND USE Good condition. Single-family residence.			
OTHER INFORMATION AS APPROPRIATE			
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC) Building Division of the City of St. Louis. Records of the City Assessor. Appraisal report of Real Estate Analysts, Ltd. Report of Cultural Resource Assessment-Archaeological Survey, University of Missouri-St. Louis. Gould's City Directory/Blue Book, 1893, 1896, 1897, and 1898. Notification from the Keeper of the National Register and the Missouri Historic Preservation Program.			
COMPILER, AFFILIATION Claude Louishomme, Project Manager			DATE July 18, 1996



HYNSON HOUSE
1314 AUBERT AVE
Saint Louis, MO


1ST FLOOR



HYNSON HOUSE
1314 AUBERT AVE
Saint Louis, MO
August 8, 1986

2ND FLOOR

< N



HYNISON HOUSE
1314 AUBERT AVE
Saint Louis, MO
August 8, 1986

ATTIC